



Ohio Revised Code

Section 1567.03 Prohibited acts.

Effective: October 29, 1995

Legislation: Senate Bill 162 - 121st General Assembly

No workman or other person shall knowingly injure a water gauge, barometer, thermometer, air course, brattice, equipment, or machinery, obstruct or throw open an airway, handle or disturb any part of the machinery of the hoisting engine of a mine, open a door of a mine and neglect to close it, endanger the mine or those working therein, disobey an order given in pursuance of law, or do a willful act which may endanger the lives and health of persons working therein, the security of a mine, or the machinery connected therewith.
